Figure 9. Sills along the entrance section of the bombproof were separated by two spacers dadoed to accept the sills.