Figure 10. Wall studs along the entrance tunnel were found to have been set into the sills using stopped dado joints.