

Figure 5.1 Comparison of Load-Displacement Curves for AASHTO Type III Girder