

Figure B.19 – Cumulative Corrosion Over Time for Bath 3, 2.0% Chloride, Post-Cracked



Figure B.20 – Cumulative Corrosion Over Time for Bath 3, 3.0% Chloride, Post-Cracked