Plate 1 (left)

View to East Showing Configuration of Entrance to Brick Bottomed Drain, Detention Center Site Area A. Note Rotted Wood Lining.

Plate 2 (center)

View to North Showing Western End of Brick Bottomed Drain (Center) with Dark Brown Silty Sand in Pond or Ravine to Left.

Plate 3 (right)

Overall View to East Showing Entire Brick Bottomed Drain After Excavation.